WILLIAMS STREET GARAGE REPAIRS ROSEMONT, IL



Project: Williams Street Parking Garage Repairs

Owner Reference: Village of Rosemont

Location: Rosemont, IL

Engineer Reference: J.V. Henik, Inc.

Scope:

- Overhead Concrete Repairs (Double-Tee, Beams, Spandrels, Corbels) (4,110 SF)
- Floor Repair (4,000 SF)
- Remove/Replace Expansion Joints (845 LF)
- Remove/Replace Sealant (Double-Tee, Horizontal, Vertical) (31,620 LF)
- > 100% Silane Sealer (120,000 SF)
- Stair Repairs
- Double-Tee Connectors at Pre-Cast to Pre-Cast Connectors (Sandblast/Paint) (5,624)
- Double Tee Connector Repair with Carbon Fiber/Epoxy (414)
- Traffic Bearing Waterproofing (10,000 SF)

Site Conditions:

> The facility remained fully operational during repairs.